


Touchstone Status
http://192.168.100.1/phy.htm
ARRIS
Status
Status
HW/FW Versions
Event Log
CM State
RF Parameters
Downstream
Freq/Power: 338.750 MHz -1 dBmV
Signal to Noise Ratio: 33 dB
Modulation: QAM256
Upstream
Freq/Power: 52.000 MHz 52 dBmV
Channel Type: DOCSIS 2.0 (ATDMA)
Symbol Rate: 5120 kSym/sec
Modulation: QAM8
Status
System Uptime: 39 days 4h:41m:40s
Computers Detected: 1
CM Status: Telephony-AC Power Iso OFF Reg Complete
WAN Isolation: OFF-Access to WAN is allowed and button is disabled
Time and Date: SUN JUN 06 20:46:37 2010
Interface Parameters
Interface Name | Provisioned | State | Speed | MAC address
LAN | Enabled | UP | 100 (Full) | 00-00-CA-F6-91-4C
CABLE | Enabled | UP | ---- | 00-00-CA-F6-91-4D
USB | Enabled | DOWN | 12 | 00-00-CA-F6-91-4F
MTA | Enabled | UP | ---- | 00-00-CA-F6-91-4E
© Copyright 2004-2007, ARRIS Group, Inc., All rights reserved.
Date and Time Properties
Date & Time
Time Zone
Internet Time
Current time zone: W. Europe Daylight Time
OK
Cancel
Apply
start


DOCSIS(CM) Events

Date Time	Event ID	Event Level	Description
*****	20000300	3	Ranging Request Retries exhausted
*****	20000200	3	No Ranging Response received - T3 time-out
*****	20000300	3	Ranging Request Retries exhausted
*****	20000200	3	No Ranging Response received - T3 time-out
*****	20000300	3	Ranging Request Retries exhausted
*****	20000200	3	No Ranging Response received - T3 time-out
*****	20000300	3	Ranging Request Retries exhausted
*****	20000200	3	No Ranging Response received - T3 time-out
*****	20000300	3	Ranging Request Retries exhausted
*****	20000200	3	No Ranging Response received - T3 time-out
4/28/2010 16:05	1040100	6	TLV-11 - unrecognized OID
5/15/2010 23:07	8010300	5	DHCP RENEW WARNING - Field invalid in response
5/17/2010 15:12	20000200	3	No Ranging Response received - T3 time-out
5/22/2010 23:08	8010300	5	DHCP RENEW WARNING - Field invalid in response
5/23/2010 0:22	20000200	3	No Ranging Response received - T3 time-out
5/29/2010 23:08	8010300	5	DHCP RENEW WARNING - Field invalid in response
6/1/2010 2:19	20000200	3	No Ranging Response received - T3 time-out
6/2/2010 11:08	8010300	5	DHCP RENEW WARNING - Field invalid in response
6/3/2010 12:23	20000200	3	No Ranging Response received - T3 time-out
6/5/2010 23:08	8010300	5	DHCP RENEW WARNING - Field invalid in response

PACKETCABLE(MTA) Events

Date Time	Event Level	Enterprise	Event ID	Description	MAC Address	Endpoint Na
4/28/2010 16:05	5	4115	16	MTA TFTP: Successful	00:00:CA:F6:91:4E	mta5946.voip.rot.upc.nl/10
4/28/2010 16:05	5	4115	3	Voice Line State Change, Line Number = 1, Prev State = OOS, New State = IS	00:00:CA:F6:91:4E	AALN/1:mta5946.voip.rot.
4/28/2010 16:05	5	4115	3	Voice Line State Change, Line Number = 2, Prev State = OOS, New State = IS	00:00:CA:F6:91:4E	AALN/2:mta5946.voip.rot.
4/28/2010 16:05	5	4115	26	MTA PROV: Successful!	00:00:CA:F6:91:4E	mta5946.voip.rot.upc.nl/10
4/28/2010 16:05	2	4115	65530	Call Agent Loss of Communications	00:00:CA:F6:91:4E	AALN/2:mta5946.voip.rot.


Touchstone Registration St...
http://192.168.100.1/cm_state.htm
Andere bladwijzers
ARRIS
Registration Status
Status
HW/FW Versions
Event Log
CM State
CM State: Telephony-AC Power Iso OFF Reg Complete
Complete Docsis-Downstream Scanning
Complete Docsis-Downstream Ranging
Complete Docsis-Upstream Ranging
Complete Docsis-DHCP
Complete Docsis-TFTP
Complete Docsis-Data Reg Complete
Complete Telephony-DHCP
Complete Telephony-TFTP
Complete Telephony-Reg with Call Server
Complete Telephony-Reg Complete
TOD State:
Retrieved Time of Day
BPI State:
Enabled - Authorized BPI Status
DHCP Attempts to obtain CM IP Address:
12 Attempt(s)
© Copyright 2004-2007, ARRIS Group, Inc., All rights reserved.
start
Wireless Network Co...
Outlook Express
Touchstone Registrat...
WTF_een_ARRIS_ipv...
20:53


Touchstone HW/FW Versions
http://192.168.100.1/vers.htm
HW/FW Versions
Status
HW/FW Versions
Event Log
CM State
CM Hardware Information
System: ARRIS Euro-DOCSIS 2.0 / Euro-PacketCable 1.0 Touchstone Telephony Modem HW_REV: 32
VENDOR: Arris Interactive, L.L.C.
BOOTR: 5.01
SW_REV: 5.2.47
MODEL: TM402B
Product Type: 00000000 010c3182
Product Release: 00000020
Flash Part: MX29LV320BTC
Download Revision: 2
Firmware Revision: 5.2.47
Serial Number: 51WBMD21B024611
MTA Hardware Information
Mta Serial Number 51WBMD21B024611
Mta Type Identifier pktc1.0:052201010002010209010B0A0103050607080 90A0B0C0C01000D0101100109120200 01
Firmware Build and Revisions
Firmware Name: TS050247_021808_MODEL_4_5_6
Firmware Build Time: Mon Feb 18 17:09:15 EST 2008
© Copyright 2004-2007, ARRIS Group, Inc., All rights reserved.