






| | | | | |
|---|---|---|---|---|
| **Model** | EPC3000 | | | |
| **Vendor** | Cisco | | | |
| **Hardware Revision** | 1.2 | | | |
| **Serial Number** | 131004660 | | | |
| **CM Mac Address** | 00-1C-EA-A5-39-58 | | | |
| **Bootloader Revision** | 1.0.0.4 | | | |
| **Current Software Revision** | epc3000-v303r2390-090629c | | | |
| **Firmware Name** | epc3000-v303r2390-090629c.pt7b.signed | | | |
| **Firmware Build Time** | 20090629193925 | | | |
| **Receive Power Level** | 0.5 dBmV | 0.3 dBmV | 0.1 dBmV | 0.3 dBmV |
| **Signal to Noise Ratio** | 34.8 dB | 34.5 dB | 34.9 dB | 34.8 dB |
| **Transmit Power Level** | 48.5 dBmV | | | |
| **Cable Modem Status** | Operational | | | |

Cisco, Cisco Systems, and the Cisco Systems logo are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and certain other countries.


http://192.168.2.1/
Signal
http://192.168.100.1/signal.asp
Andere bladwijzers
System
Signal
Status
Log
Setup
Signal
This page provides important information about the status and quality of the communications between your cable modem and the cable modem network.
Downstream Channel
The data shown in the table below provides information about the signal coming from the network to your cable modem.
Channel ID 32 33 34 35
Dowastream Frequency 306.75 Mhz 314.75 Mhz 322.75 Mhz 330.75 Mhz
Modulation 256QAM 256QAM 256QAM 256QAM
Power Level 0.5 dBmV 0.2 dBmV -0.1 dBmV 0.3 dBmV
Signal to Noise Ratio 34.8 dB 34.6 dB 34.9 dB 34.8 dB
Upstream Channel
The data shown in the table below provides information about the signal being transmitted to the network from your cable modem.
Channel ID 5
Upstream Frequency 52.00 Mhz
Modulation 8QAM
Bit Rate 15360 Kbps
Power Level 48.5 dBmV
Cisco, Cisco Systems, and the Cisco Systems logo are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and certain other countries.
start
Inbox - Outlook Express
Signal - Google Chrome
Document1 - Microsof...
15:03


http://192.168.2.1/
Status
http://192.168.100.1/status.asp
Andere bladwijzers
CISCO
System
Signal
Status
Log
Setup
Status
This page provides important information about the operational status of your cable modem and the device(s) you have connected to it.
Cable Modem
The data shown in the table below provides information about the operational status of your cable modem.
Cable Modem Status
Operational
Cable Modem IP Address
10.7.27.177
Current Time
Mon Jun 07 2010 15:04:03
Time Since Last Reset
0 days 0h:7m:14s
Configuration File
cm_90mbps.cm
Cable Modem Certificate
Installed
Ethernet
The data shown in the table below provides information about ethernet.
LINK Status
UP
LINK Speed
100
LINK Duplex
Full
Cisco, Cisco Systems, and the Cisco Systems logo are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and certain other countries.
start
Inbox - Outlook Express
Status - Google Chrome
Document1 - Microsof...
15:04

# Log


http://192.168.100.1/log.asp
CISCO
System
Signal
Status
Log
Setup
DOCSIS(CM) Events
The data shown in the table below provides information about the DOCSIS events of your cable modem.
Time | ID | Level | Description
Tue May 25 06:06:18 2010 | 68010600 | 6 | DHCP Renew - lease parameters modified time server 212.142.39.136; modifie;CM-MAC=00:1c:ea:a5:39:58;CMTS-MAC=00:14:f1:e9:41:b4;CM-QOS=1.1;CM-VER=3.0;
Thu Jan 1 00:00:13 1970 | 84020100 | 4 | Missing Mandatory MDD TLV on primary DS Channel;CM-MAC=00:1c:ea:a5:39:58;CMTS-MAC=00:14:f1:e9:41:b5;CM-QOS=1.1;CM-VER=3.0;
Sun Jun 6 10:38:23 2010 | 73040100 | 6 | TLV-11 - unrecognized OID;CM-MAC=00:1c:ea:a5:39:58;CMTS-MAC=00:14:f1:e9:41:b4;CM-QOS=1.1;CM-VER=3.0;
Thu Jan 1 00:00:14 1970 | 84020100 | 4 | Missing Mandatory MDD TLV on primary DS Channel;CM-MAC=00:1c:ea:a5:39:58;CMTS-MAC=00:14:f1:e9:41:b5;CM-QOS=1.1;CM-VER=3.0;
Sun Jun 6 17:07:11 2010 | 73040100 | 6 | TLV-11 - unrecognized OID;CM-MAC=00:1c:ea:a5:39:58;CMTS-MAC=00:14:f1:e9:41:b4;CM-QOS=1.1;CM-VER=3.0;
Thu Jan 1 00:00:13 1970 | 84020100 | 4 | Missing Mandatory MDD TLV on primary DS Channel;CM-MAC=00:1c:ea:a5:39:58;CMTS-MAC=00:14:f1:e9:41:b5;CM-QOS=1.1;CM-VER=3.0;
Thu Jan 1 00:00:23 1970 | 82000200 | 3 | No Ranging Response received - T3 time-out;CM-MAC=00:1c:ea:a5:39:58;CMTS-MAC=00:14:f1:e9:41:b4;CM-QOS=1.1;CM-VER=3.0;
Sun Jun 6 20:28:18 2010 | 73040100 | 6 | TLV-11 - unrecognized OID;CM-MAC=00:1c:ea:a5:39:58;CMTS-MAC=00:14:f1:e9:41:b4;CM-QOS=1.1;CM-VER=3.0;
Thu Jan 1 00:00:14 1970 | 84020100 | 4 | Missing Mandatory MDD TLV on primary DS Channel;CM-MAC=00:1c:ea:a5:39:58;CMTS-MAC=00:14:f1:e9:41:b5;CM-QOS=1.1;CM-VER=3.0;
Mon Jun 7 08:23:03 2010 | 73040100 | 6 | TLV-11 - unrecognized OID;CM-MAC=00:1c:ea:a5:39:58;CMTS-MAC=00:14:f1:e9:41:b4;CM-QOS=1.1;CM-VER=3.0;
Mon Jun 7 12:27:31 2010 | 84020200 | 5 | Lost MDD Timeout;CM-MAC=00:1c:ea:a5:39:58;CMTS-MAC=00:14:f1:e9:41:b4;CM-QOS=1.1;CM-VER=3.0;
Mon Jun 7 12:27:45 2010 | 82000400 | 3 | Received Response to Broadcast Maintenance Request, But no Unicast Maintenance opportunities received - T4 time out;CM-MAC=00:1c:ea:a5:39:58;CMTS-MAC=00:14:f1:e9:41:b4;CM-QOS=1.1;CM-VER=3.0;
Mon Jun 7 12:33:48 2010 | 82000200 | 3 | No Ranging Response received - T3 time-out;CM-MAC=00:1c:ea:a5:39:58;CMTS-MAC=00:14:f1:e9:41:b4;CM-QOS=1.1;CM-VER=3.0;
Mon Jun 7 12:37:59 2010 | 68000100 | 3 | DHCP FAILED - Discover sent, no offer received;CM-MAC=00:1c:ea:a5:39:58;CMTS-MAC=00:14:f1:e9:41:b4;CM-QOS=1.1;CM-VER=3.0;
Mon Jun 7 12:43:42 2010 | 82000200 | 3 | No Ranging Response received - T3 time-out;CM-MAC=00:1c:ea:a5:39:58;CMTS-MAC=00:14:f1:e9:41:b4;CM-QOS=1.1;CM-VER=3.0;
Mon Jun 7 12:46:56 2010 | 82000900 | 5 | B-INIT-RNG Failure - Retries exceeded;CM-MAC=00:1c:ea:a5:39:58;CMTS-MAC=00:14:f1:e9:41:b4;CM-QOS=1.1;CM-VER=3.0;
Mon Jun 7 12:46:59 2010 | 82000200 | 3 | No Ranging Response received - T3 time-out;CM-MAC=00:1c:ea:a5:39:58;CMTS-MAC=00:14:f1:e9:41:b4;CM-QOS=1.1;CM-VER=3.0;
Mon Jun 7 12:49:18 2010 | 82000900 | 5 | B-INIT-RNG Failure - Retries exceeded;CM-MAC=00:1c:ea:a5:39:58;CMTS-MAC=00:14:f1:e9:41:b4;CM-QOS=1.1;CM-VER=3.0;
Mon Jun 7 12:49:19 2010 | 82000200 | 3 | No Ranging Response received - T3 time-out;CM-MAC=00:1c:ea:a5:39:58;CMTS-MAC=00:14:f1:e9:41:b4;CM-QOS=1.1;CM-VER=3.0;
Mon Jun 7 12:52:48 2010 | 73040100 | 6 | TLV-11 - unrecognized OID;CM-MAC=00:1c:ea:a5:39:58;CMTS-MAC=00:14:f1:e9:41:b4;CM-QOS=1.1;CM-VER=3.0;
Refresh
Clear
Cisco, Cisco Systems, and the Cisco Systems logo are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and certain other countries.